Summary of Errata and Clarifications to the HDCP on HDMI Specification Rev 2.3

Throughout the specification, delete all references to the 20 ms watchdog timer defined under Section 2.3.

Page 11, replace the second bullet point under Second 2.1 with the following

• Locality Check - The HDCP Transmitters performs a locality check with the HDCP Receiver.

Page 16, replace the second bullet point under Section 2.3 with the following

• The LC_Send_L_prime message may be received by the transmitter.

Page 16, replace the fourth bullet point under Section 2.3 with the following

• Compares L and L' if LC_Send_L_prime message is received from the receiver, and locality check fails if L is not equal to L'.

Page 17, delete references to "Set watchdog timer" and "Within 20 ms" in Figure 2.4.

Page 17, replace the second bullet point with the following

• Makes LC_Send_L_prime message containing 256-bit L^\prime available for the transmitter to read immediately after computation of L^\prime .

Page 17, replace the first sentence in paragraph 3 with the following

If the transmitter receives the LC_Send_L_prime message and in the case of a locality check failure due to mismatch of L and L' at the HDCP Transmitter, locality check may be reattempted by the HDCP Transmitter for a maximum of 1023 additional attempts(for a maximum allowed 1024 total trials) with the transmission of an LC_Init message containing a new r_n .

- Page 36, replace paragraph 13 with the following Transition F2:F0. This transition occurs on one or more consecutive locality check failures. If the downstream side receives the LC_Send_L_prime message, locality check fails due to mismatch of L and L' at the downstream side.

Page 59, delete the paragraph under Section 4.2.8.