Digital Content Protection LLC

1) Merged HDCP Rev 1.1 errata

2) Changes to repeater re-authentication requirements
Under Section 2.5 in HDCP Specification 1.2 -
      First paragraph in Page 26
      Third paragraph in Page 27
From "NOTE: Optionally, the upstream connection need not…" to "re-authenticate the attached HDCP receiver"

3) New SRM proposal
Under Section 5 in HDCP Specification 1.2 – Pages 54 – 56

4) Timing diagram to illustrate clearly the 58th pixel clock timing requirement
Appendix D in HDCP Specification 1.2 – Fig. D-2 in Page 87

5) Ri check (Link Integrity Check) recommendation
Appendix E in HDCP Specification 1.2 – Page 88