

Summary Errata and Clarifications to the HDCP Revision 2.3 on HDMI Compliance Test Specification

Page 36 (1B-01-1)

Replace:

- If DUT does not transmit RepeaterAuth_Send_Ack message within 1 s, then FAIL (Ref-1B-2)

With:

- If DUT does not transmit RepeaterAuth_Send_Ack message within two seconds, then FAIL (Ref-1B-2)

Page 50 (1B-09-1)

Replace:

- If DUT does not transmit RepeaterAuth_Send_Ack message within 1 second, then FAIL (Ref-1B-2)

With:

- If DUT does not transmit RepeaterAuth_Send_Ack message within two seconds, then FAIL (Ref-1B-2)

Page 128 Ref-1B-2

Add:

Reference	Requirement
State A8: Send Receiver ID list acknowledgement	The RepeaterAuth_Send_Ack message must be received by the HDCP Repeater within two seconds from the time the READY status was asserted by the HDCP Repeater.